




A detailed line drawing of a mechanical assembly. It features a vertical rod with a curved top. A horizontal bar is attached to the rod, with two sets of components labeled 'N' and 'O' on either side. At the bottom, a circular base is shown with a complex mechanism. Labels 'J' and 'P' point to specific parts of this mechanism. A label 'K' points to a component on the right side of the base, and a label 'L' points to a component on the left side of the base. A label 'U' points to a component on the right side of the vertical rod.

