



109X4

 $\Phi 4 \times 16$

119X1



117X1

 $\Phi 25, L=170$ 


2

102X10



L=40

119X1




104X4



L=28

105X4

 $\Phi 6 \times 30 \text{mm}$ 


3

108X4



Φ4X12

119X1



116X2




L=300

116A



116B

4




108X4



Φ4X12

119X1



116X2




L=300

116A





116B




5





6




7






101X10	119X1	103X4
		
Φ 15*12mm		Φ 12


10




112X4	119X1
	
M6x25	

11




108X8	119X1
	
Φ4X12	


116X4	
 L=300	



12


108X8	119X1
	
Φ4X12	


116X4	
 L=300	




13


16



103X8	119X1	105X4
		
Φ 12		Φ 6X30mm
104X8	114X2	115X2
		
L=28	M4x25	




17


103X8	119X1	105X4
		
Φ 12		Φ 6X30mm
104X8	114X2	115X2
		
L=28	M4x25	












119X1	124X4	120X4	121X2
	 Ø4X40	 Ø4X14	
122X4	123X4		
			

20



PART NO.		PART NAME	QUANTITY
1			1
2			1
3			1
4			1
5			1
6			1
7			1
8			1
9			1
10			1
11			2
12			2
13			4
14			4
15			4
16			4
17			2
18			4
19			2

HARDWARE NO.	PHOTOGRAPH OF PART	DESCRIPTION/SIZE	NO OF PCS
101		$\Phi 15 \times 12 \text{mm}$	20
102		L=40	20
103		$\Phi 12$	24
104		L=28	24
105		$\Phi 6 \times 30 \text{mm}$	32
106		$\Phi 10$	8
107		$\Phi 5 \times 50$	8
108		$\Phi 4 \times 12$	40
109		$\Phi 4 \times 16$	4
110		9207	4
111		$\Phi 7 \times 70$	12
112		M6x25	4
113			2
114		M4x25	6
115			6
116		L=300, 宽45	4
117		$\Phi 25, L=170$	1
118		M4	1
119			1
120		$\Phi 4 \times 14$	28
121			2
122			4
123			4
124		$\Phi 4 \times 40 \text{mm}$	4