


























Parts List

1 	1	2 	2	3 	1	4 	2
5 	1	6 	1	7 	1	8 	1
9 	1	10 	1	11 	2	12 	1
13 	1	14 	1	15 	1	16 	1
17 	1	18 	2	19 	2	20 	1
21 	1	22 	1	23 	2	24 	1
25 	1						

Hardware List

A



M6x40mm

78+2PCS

B



Ø15x9mm

78+2PCS

C



Ø6x30mm

58+2PCS

D



Ø6x50mm

2PCS

E



1PCS

F



M3x14mm


60+2PCS

G



4PCS

H




2PCS

J



8PCS

K




2PCS

L




28+2PCS

M




1PCS

N



1PCS

P




10PCS


Q




16PCS




STEP 1




	Ax4PCS
	Bx4PCS




STEP 2




	Ax4PCS
	Bx4PCS




STEP 3



	Ax8PCS
	Bx8PCS




STEP 4




	Ax14PCS
	Cx12PCS


STEP 5



	Px10PCS
	Cx14PCS




STEP 6



	Ax8PCS
	Cx12PCS

STEP 7




Ax5PCS




Cx4PCS


STEP 8




Bx3PCS




STEP 9




	Bx3PCS
	Ax5PCS
	Cx4PCS




STEP 10



	Bx4PCS
--	--------




STEP 11




	Gx4PCS
	Ax6PCS
	Cx4PCS
	Fx8PCS


STEP 12




	Bx6PCS
---	--------




STEP 13




Bx8PCS



STEP 14




STEP 15




	Hx2PCS
	Fx4PCS
	Cx8PCS
	Ax8PCS


STEP 16



	Bx8PCS
---	--------




STEP 17




	Dx2PCS
	Cx6PCS
	Ax6PCS
	Ex1PCS
	Fx2PCS


STEP 18




	Ax4PCS
	Bx4PCS




STEP 19




Bx6PCS



STEP 20




STEP 21




	Cx8PCS
	Ax6PCS


STEP 22



	Bx6PCS
---	--------




STEP 23



Jx8PCS

STEP 24



Kx2PCS




Hx2PCS




Fx4PCS

STEP 25




Fx8PCS

STEP 26






Fx6PCS

STEP 27




	Fx28PCS
	Lx28PCS

STEP 28



	Nx1PCS
---	--------

STEP 29



Qx16PCS