







Assembly Instruction






Panel No	Panel Sizes	Quantity		Panel No	Panel Sizes	Quantity
1	1600*400*16	1		9	529*525*5	2
2	1600*400*16	1		10	529*517*5	1
3	518*399*16	1		11	519*170*16	3
4	518*399*16	1		12	464*120*12	3
5	518*382*16	1		13	350*120*12	3
6	518*382*16	1		14	350*120*12	3
7	503*350*16	1		15	475*349*5	3
8	511*350*16	1		16	514*519*16	2




Fittings



A=16



B=16




C=16



D=40



E=12




F=1



M6*16

G1=16




M6*30

G2=1



H=1




I-2=2

I-3=2

I-1=4

V2=24




J-1=2


J-4=1

J-3=1

J-2=2



L=8



N=3




O=24



P=24



T=2



U=5



M3.5*12

V1=24




Z1=8




Z2=8


1




2




3




4




5




6




7




8




9




10




11






12



13




14




X3

15



16



17

